

WEEKLY INCIDENT SUMMARY

Week ending Friday 17 July 2020

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of recent incidents and our comments to operators.

TYPE	NUMBER
Reportable incident total	45
Summarised incident total	3

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0037768 Open cut metalliferous mine	A plant operator was installing an interstage screen using a gantry crane. During the lowering process, the operator noticed that a locking pin was in the closed position, causing an obstruction. As the operator opened the locking pin, the screen (load) moved and crushed the operator's finger between the screen body and the locking pin.	Mine operators and PCBUs should review their procedures and training packages to ensure they include the potential hazards associated with placing body parts on solid objects around moving parts and material.



Dangerous
incident
IncNot0037752
Underground
metalliferous
mine



Roads or other
vehicle operating
areas

While tramping down a decline, a truck's brakes failed. The truck bounced off the left and right-hand walls before the operator turned it into the wall to stop it.

The operator had conducted a pre-start check and the brakes were confirmed to be working.



This incident is under investigation and the reason for the brake failure was unknown at the time of publication.

Mines are reminded of the requirement to have thorough lifecycle management plans for all equipment, including operation and maintenance procedures.

When work is carried out on a safety-critical system, appropriate work verification procedures must be in place.

Dangerous
incident
IncNot0037742
Quarry

A worker was about to use a 240 volt pressure washer when he suffered an electric shock. An examination of the pressure washer revealed a damaged power cord.

Mine operators must have systems and checks in place for workers to carry out pre-use inspections of portable electrical equipment and monitor worker compliance.

Workers must inspect equipment before operating it to ensure it is fit-for-purpose and free from damage. Power leads should be



fully unwound and checked for damage before being plugged in.

Damaged equipment should be reported and managed in accordance with the mine’s defect management system.

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
International (fatal)	
MSHA	<p>Mine fatality</p> <p>On 19 June 2020, a miner died while inspecting a stockpile for oversized material. As the miner walked along the toe of the stockpile, a portion of the stockpile collapsed, covering him with about 1.2 metres of material.</p> <p>Details</p>
International (other, non-fatal)	
MinEx NZ	<p>Uncontrolled movement of excavator – need to ensure fundamentally stable parking</p> <p>An operator was exiting his excavator when he noticed the boom moving. He had not lowered the boom and it was not in safety mode so the boom was able to move freely.</p> <p>He quickly re-entered the excavator and lowered the boom into safety mode.</p> <p>Details</p>

National (fatal)

**NT WorkSafe
(in MinEx)**

Chain failure fatally injures worker

A worker was operating an excavator to tow another excavator, which had broken down. A chain was attached to the chassis (frame) of the broken-down excavator and to the quick clamp of the other excavator. The excavator being towed weighed about 36 tonne.

When the chain broke, it recoiled, striking the worker who was sitting in the excavator cabin.

[Details](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2020 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (July 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference DOC20/588096

Mine safety reference ISR20-29

Date published 24 July2020

Approved by Chief Inspector
Office of the Chief Inspector