



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS

HEALTH & SAFETY
spanning the
Mineral Products Industry

Login Register Information



INCIDENT ALERT

LOCATION:	MOBILE PLANT	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	11/08/2011
SUB ACTIVITY:	N/A	INCIDENT No:	00294

TITLE

Fall from mobile plant

ACCIDENT / INCIDENT DETAILS

An employee suffered a fracture to his arm after falling 3 metres from his vehicle whilst attempting to descend via the emergency exit ladder. The normal means of access and egress was by a stairway with a retractable bottom section, due to mechanical problems this was not working. Investigation identified that the fault with the normal access route had been unresolved for some time and it had become normal practice to use the emergency route. The gate at the top of the emergency ladder was also faulty with the catch not properly aligned causing difficulty when releasing it. It was whilst trying to release this catch that the employee apparently fell, toppling over the gate and falling to the ground. Other factors identified were that the employee may have been carrying a plastic container at the time and would have been unable to maintain 3 points of contact.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



Driver fell from top of emergency exit ladder

Click image to enlarge



Close up of gate at top of emergency exit ladder

LEARNING POINTS / ACTIONS TAKEN

Learning Points

The dumper was fitted with a modern access stairway which due to a fault was out of use. Whilst alternative access was identified via the emergency exit the risks from this were not fully identified. The alternative arrangements should only have been a short term solution in fact were allowed to persist for several months.

Prompt maintenance – Is safety related maintenance prioritised / tracked? Are contractors / suppliers made aware of the critical nature of some jobs?

Risk Assessment – Are alternative solutions thoroughly assessed? Does the assessment involve the people engaged in the task?

Hazard Alert – Is everyone engaged in reporting near misses and hazards? Does everyone fully understand the need to highlight hazards? Are alerts responded to with feedback to the originator in a timely manner?

Get a Grip – Is everyone aware of the need for 3 points of contact when using steps and ladders? Is it common practice or only when being watched? Are discrete observations made to ensure that it is an ingrained behaviour?

LEARNING POINTS / ACTIONS IMAGES

[Request Futher Information](#) **[additional informat](#)**[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us ar us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy content of this website, this cannot be guaranteed. [Click here](#) for full terms.