



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



Login

Register

Information basket

Home

About this site

BEST PRACTICE

INCIDENT ALERTS

HOT TOPICS & GUIDANCE

TOOLBOX TALKS

CPD reports

Links

INCIDENT ALERT

LOCATION:
ACTIVITY:
SUB ACTIVITY:

COMPANY-WIDE
MAINTENANCE & HOUSEKEEPING
N/A

ALERT STATUS:
DATE ISSUED:
INCIDENT No:

Normal
02/12/2011
00317

TITLE

Fire: flammable substance close to oxy-propane cutting activity

ACCIDENT / INCIDENT DETAILS

A conveyor was to be removed from the location where it was situated and was to be subsequently relocated in a new position. As part of the dismantling process, a canopy needed to be removed. The maintenance engineer utilised oxy-Propane cutting equipment to cut the canopy away from the conveyor structure.

An oil drum storage bund was situated within a few metres and spilled oil had accumulated in the catch-tray. The maintenance engineer believed the oil to be water based and non-flammable. This assumption was incorrect.

As cutting commenced, sparks landed in the spill tray igniting the oil. The fire caused localised damage, however; the proximity of the bund to the access stairs used by the engineer to the workplace meant the fire trapped him temporarily. A colleague positioned a ladder permitting his escape.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



canopy

Click image to enlarge



oil storage bund

LEARNING POINTS / ACTIONS TAKEN

- Before any hot work assess the area for potentially flammable substances.
- Conduct a suitable and sufficient risk assessment.
- Complete a permit to work appropriate to the task.
- Ensure you have an effective escape route available to you.

LEARNING POINTS / ACTIONS IMAGES

[Request Futher Information](#)

 [convert this page to a pdf](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.