



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS

HEALTH & SAFETY
spanning the
Mineral Products Industry

Login Register Information



INCIDENT ALERT

LOCATION:	ROAD TRANSPORT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	09/05/2011
SUB ACTIVITY:	N/A	INCIDENT No:	00289

TITLE

Potential Mixer Drum Entanglement

ACCIDENT / INCIDENT DETAILS

A serious incident occurred recently during the washing down of a mixer drum following discharged concrete. It is believed that the cause of this incident was the type of tap (see picture).

The design of the tap, and dependant on where an individual washes the blades, could result in the tap becoming wedged in the mixer blade, pulling the hose and potentially the individuals hands/arm into the mixer.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



Mixer Tap

LEARNING POINTS / ACTIONS TAKEN

These types of taps should be replaced with twist on/off taps.

Mixers should only be washed in discharge mode.

All 'guarding' of mixers should be assessed to ensure that it is adequate if a hose should become trapped.

LEARNING POINTS / ACTIONS IMAGES

[Request Further Information](#)

[pdf document a](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.