



HEALTH & SAFETY
spanning the
Mineral Products Industry

[REGISTER TODAY TO RECEIVE THE LATEST UPLOADS](#)

[Login](#)

[Register](#)

[Information basket](#)

[Home](#)

[About this site](#)

[BEST PRACTICE](#)

[INCIDENT ALERTS](#)

[HOT TOPICS & GUIDANCE](#)

[TOOLBOX TALKS](#)

[CPD reports](#)

[Links](#)

INCIDENT ALERT

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT / DELIVERY	DATE ISSUED:	26/02/2010
SUB ACTIVITY:	PRODUCT DELIVERY	INCIDENT No:	00255

TITLE

Truckmixer driver hit by chute

ACCIDENT / INCIDENT DETAILS

A tipper truck fitted with a hiab arm and grab needed to be loaded from a mixer truck at a concrete plant.

The plan of how the material would be placed in the tipper truck was not fully discussed.

The problem caused by the high sides on the tipper truck and how they would interfere with the swing of the mixer chute was not fully appreciated by the tipper driver.

No member of staff was nominated to control the operation and consequently the tipper truck driver made his own decision on when to move off.

The tipper truck struck the chute which swung and injured the mixer truck driver.

(see additional pdf document for further details)



ACCIDENT / INCIDENT IMAGES

LEARNING POINTS / ACTIONS TAKEN

Clear communications and actions should be established before commencing operations.

LEARNING POINTS / ACTIONS IMAGES

[Request Further Information](#)

 [pdf document available](#)
 [additional pdf document](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.