

# Safety bulletin

Mines

Mines Inspectorate

Safety bulletin no. 100 (Version 1)  
23 August 2010

## Retrofit advice for some Haulotte mobile elevating work platforms.

### Background.

An incident involving a work platform occurred at a minesite. Whilst two workers were on the work platform, the platform crept slowly upwards approximately 0.5 metres of its own accord before the emergency stop was activated by one of the workers. Although Haulotte Australia had circulated a retrofit notice, this unit did not have the retrofit installed that may have prevented this incident. This uncontrolled movement could cause entrapment underneath a structure in other circumstances.

### Comments:

The purpose of this safety alert is to assist Haulotte Australia in alerting all present owners and users that some Haulotte mobile elevating work platforms must have the retrofit fitted. Haulotte Australia has already sent out the advice about the retrofit and is sending out a follow-up notice. However, due to the fact that original ownership may have changed there could be some new owners still unaware of this information. The units concerned have valves manufactured before week 18 of 2008.

The following list of affected units in Queensland has been provided by Haulotte Australia and was current on 30 July 2010. Haulotte Australia Pty Ltd may be contacted by telephone on 03 9792 1000 or by email [sales@haulotte.com.au](mailto:sales@haulotte.com.au)

Job No.	Serial No.	Subsidiary company	State	Model
A258165	AD115154	All Areas Rentals	Queensland	HA16PX
A258188	AD115183	All Areas Rentals	Queensland	HA18PX
A258220	AD115220	All Areas Rentals	Queensland	HA16PX
A258869	AD115996	All Areas Rentals	Queensland	HA41PX
A259132	AD116304	All Areas Rentals	Queensland	HA18PX
A259144	AD116318	All Areas Rentals	Queensland	HA260PX
A259409	AD116629	All Areas Rentals	Queensland	HA18PX
A259412	AD116632	All Areas Rentals	Queensland	HA18PX
A259497	AD116747	All Areas Rentals	Queensland	HA16PX
A264745	TD104525	All Areas Rentals	Queensland	H16TPX
A264773	TD104555	All Areas Rentals	Queensland	H16TPX
A264783	TD104565	All Areas Rentals	Queensland	H16TPX
A264784	TD104566	All Areas Rentals	Queensland	H16TPX
A264787	TD104569	All Areas Rentals	Queensland	H16TPX
A264799	TD104581	All Areas Rentals	Queensland	H25TPX
A264819	TD104601	All Areas Rentals	Queensland	H16TPX

<b>Job No.</b>	<b>Serial No.</b>	<b>Subsidiary company</b>	<b>State</b>	<b>Model</b>
A265097	TD104887	All Areas Rentals	Queensland	H25TPX
A265388	TD105196	All Areas Rentals	Queensland	H16TPX
A264183	TD103944	All Type Welding	Queensland	H23TPX
A263966	TD103724	Brisbane Brace	Queensland	H16TPX
A263984	TD103742	Brisbane Brace	Queensland	H16TPX
A256700	AD113374	Australian Independent Hire	Queensland	HA18PX
A257597	AD114469	Australian Independent Hire	Queensland	HA18PX
A264182	TD103943	Australian Independent Hire	Queensland	H23TPX
A264305	TD104066	Australian Independent Hire	Queensland	H23TPX
A251934	AD107797	Flexi Hire	Queensland	HA18PX
A252074	AD107953	Flexi Hire	Queensland	HA18PX
A252661	AD108628	Flexi Hire	Queensland	HA26PX
A253505	AD109588	Flexi Hire	Queensland	HA26PX
A253511	AD109595	Flexi Hire	Queensland	HA18PX
A253512	AD109596	Flexi Hire	Queensland	HA18PX
A253578	AD109674	Flexi Hire	Queensland	HA18PX
A253991	AD110167	Flexi Hire	Queensland	HA18PX
A254763	AD111055	Flexi Hire	Queensland	HA18PX
A254850	AD111157	Flexi Hire	Queensland	HA26PX
A254910	AD111225	Flexi Hire	Queensland	HA18PX
A255696	AD112170	Flexi Hire	Queensland	HA18PX
A256458	AD113078	Flexi Hire	Queensland	HA18PX
A256460	AD113080	Flexi Hire	Queensland	HA18PX
A256758	AD113443	Flexi Hire	Queensland	HA18PX
A256862	AD113566	Flexi Hire	Queensland	HA18PX
A258906	AD116041	Flexi Hire	Queensland	HA260PX
A261386	AD119067	Flexi Hire	Queensland	HA18PX
A261464	AD119172	Flexi Hire	Queensland	HA18PX
A261509	AD119227	Flexi Hire	Queensland	HA18PX
A262395	AD120509	H&A Sciani	Queensland	HA18PX
A261672	AD119447	Handy Hire	Queensland	HA18PX
A262296	AD120351	Handy Hire	Queensland	HA16PX
A262808	AD121369	Handy Hire	Queensland	HA18PX
A260520	AD117997	McBryde Enterprise	Queensland	HA20PX
A253021	AD109045	QLD Access	Queensland	HA18PX
A253097	AD109129	QLD Access	Queensland	HA16PX
A253103	AD109135	QLD Access	Queensland	HA16PX
A254298	AD110519	QLD Access	Queensland	HA16PX
A254764	AD111056	QLD Access	Queensland	HA18PX
A255499	AD111937	QLD Access	Queensland	HA18PX
A255501	AD111939	QLD Access	Queensland	HA18PX
A255686	AD112158	QLD Access	Queensland	HA18PX
A256310	AD112903	QLD Access	Queensland	HA18PX
A257600	AD114472	QLD Access	Queensland	HA18PX
A257753	AD114660	QLD Access	Queensland	HA16PE
A262858	AD121481	QLD Access	Queensland	HA18PX
A263525	TD103235	QLD Access	Queensland	H23TPX
A263549	TD103260	QLD Access	Queensland	H16TPX
A263580	TD103305	QLD Access	Queensland	H23TPX
A264796	TD104578	Richards Steel Fabrication	Queensland	H16TPX
A264857	TD104639	Sold	Queensland	H25TPX

**Rob O'Sullivan**  
**Chief Inspector of Mines**

Contact: Richard Horsburgh, Inspector of Mines, +61 7 40957023

**Please ensure all relevant people in your organisation receive a copy of this Safety bulletin. Any such advice supplied to site should reach those who require it, and it should also be placed on the mine notice boards.**

**See more Safety alerts and Safety bulletins at**  
[www.dme.qld.gov.au/mines/safety\\_information\\_\\_\\_bulletins.cfm](http://www.dme.qld.gov.au/mines/safety_information___bulletins.cfm)