



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



Login Register Information basket

Home

About this site

BEST PRACTICE

INCIDENT ALERTS

HOT TOPICS & GUIDANCE

TOOLBOX TALKS

CPD reports

Links

INCIDENT ALERT

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	31/03/2011
SUB ACTIVITY:	N/A	INCIDENT No:	00286

TITLE

Over-Turned Vibratory Roller

ACCIDENT / INCIDENT DETAILS

During routine site operations ; a Bomag 135 (small tandem vibratory roller) was being driven along a small country lane to collect water from a standpipe. The lane was narrow, cambered and with steep undulations, there was also an area of super elevation.

As the roller was being driven along one of these super elevated sections, one of the rolls lost contact with the road surface causing it to traverse down the lane. As it did so, it began gathering soil from the verge into the rear drum - to such an extent that it over turned the machine - with the operator still on board.

The operator was saved from serious injury due to two key safety devices.

- the seat belt prevented him from falling from the seat and underneath the roller.

- the ROPS (Roll Over Protection System) was in place protecting the machine from rolling completely over and protected the operators upper body and head.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



Overtuned Roller 1

Click image to enlarge



Overtuned Roller 2

LEARNING POINTS / ACTIONS TAKEN

- ALWAYS WEAR YOUR SEAT BELT - ENSURE IT IS FUNCTIONAL
- CHECK THE ROPS STRUCTURE DAILY - ENSURE IT IS FIXED IN POSITION - NO DEFECTS
- SURVEY TRAVEL ROUTES PRIOR TO EMBARKING WHENEVER POSSIBLE
- KEEP YOUR TRAVEL SPEED LOW ENOUGH FOR YOU TO REACT TO UNEXPECTED SITUATIONS
- REPORT DEFECTS IMMEDIATELY



LEARNING POINTS / ACTIONS IMAGES

Click image to enlarge



Roller

[Request Futher Information](#)

 [pdf document available](#)
 [additional pdf document](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.