



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



Login

Register

Information basket

Home

About this site

BEST PRACTICE

INCIDENT ALERTS

HOT TOPICS & GUIDANCE

TOOLBOX TALKS

CPD reports

Links

INCIDENT ALERT

LOCATION: CONSTRUCTION/DELIVERY SITE
 ACTIVITY: PRODUCTION AND PROCESSING
 SUB ACTIVITY: AGGREGATE PROCESSING

ALERT STATUS: Normal
 DATE ISSUED: 16/08/2011
 INCIDENT No: 00298

TITLE

Articulated Dumper Cab Overturn

ACCIDENT / INCIDENT DETAILS

An Articulated dumper cab turned over whilst attempting to reverse down a slope with the cab at 90 degrees to the rear body. The driver suffered bruising to his right thigh and was prevented from further injury as he was wearing his seatbelt.

Whilst attempting to reverse down the slope the driver had his cab angled at 90 degrees to the trailer section which was positioned down the slope. Due to the width of the flat area at the top of the slope and the area being driven and turned on several times, depressions had appeared.

The front left hand side wheels were just off the flat area and on to the slope. The front left wheel went into a depression causing the cab to dip, due to this the weight of the rear body and its load caused the rear to drag the cab over and then slide approx 6 metres down the slope.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



Slope

Click image to enlarge



Overturned Cab

LEARNING POINTS / ACTIONS TAKEN

This accident could have been prevented by:

- the tip area being a more suitable grade for the operation and the operation better planned
- a more stringent inspection regime of the tip area by site managers, supervisors and drivers

LEARNING POINTS / ACTIONS IMAGES

[Request Further Information](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.