



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS

HEALTH & SAFETY
spanning the
Mineral Products Industry

Login

Register

Information basket

▶ Home

▶ About
this site

▶ BEST
PRACTICE

▶ INCIDENT
ALERTS

▶ HOT TOPICS
& GUIDANCE

▶ TOOLBOX
TALKS

▶ CPD
reports

▶ Links

INCIDENT ALERT

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	01/03/2011
SUB ACTIVITY:	FACE ACTIVITY	INCIDENT No:	00283

TITLE

Blasting during Freezing Conditions

ACCIDENT / INCIDENT DETAILS

A blast took place at an Opencast Coal Quarry in West Glamorgan, South Wales, that caused flyrock to project outside the site's 150 metre danger zone. The weather conditions were dry, sunny and freezing and that day was regarded as the coldest day during two weeks of freezing conditions.

The incident was reported to the Health and Safety Executive although it was not reportable under RIDDOR, as the flyrock did not project beyond the site boundary. No injury occurred as a consequence of this incident.

The stemming in one hole or possibly two of the holes had failed because of the extremely cold conditions. It has been custom and practice for many years to water the blast area prior to firing in order to suppress the dust. The blast area on this occasion was watered approximately 90 minutes before firing. It had been noticed that water had frozen around the drill holes.

The operating company had never before experienced this type of incident. On investigation, it was concluded that ice formed in and around the stemming and the side of the shot hole and as there was no cohesion between the stemming and the side of the shothole. The stemming was ejected on firing, in turn causing flyrock to be projected outside the danger zone.

ACCIDENT / INCIDENT IMAGES

LEARNING POINTS / ACTIONS TAKEN

The following additional controls have subsequently been introduced for blasting in freezing conditions:-

- Watering of blast areas to be suspended during freezing or near freezing conditions.
- Stockpiles of chippings to be covered with tarpaulins to prevent freezing.
- Firing to take place as soon as possible after stemming the holes.
- Danger zones to be extended in freezing or near freezing conditions.

LEARNING POINTS / ACTIONS IMAGES

[Request Further Information](#)

[pdf document available](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.