



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



Login

Register

Information basket

Home

About this site

BEST PRACTICE

INCIDENT ALERTS

HOT TOPICS & GUIDANCE

TOOLBOX TALKS

CPD reports

Links

INCIDENT ALERT

LOCATION:	CONCRETE PRODUCTS	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT / DELIVERY	DATE ISSUED:	07/04/2011
SUB ACTIVITY:	PRODUCT DELIVERY	INCIDENT No:	00288

TITLE

Concrete Delivery Incident

ACCIDENT / INCIDENT DETAILS

During a delivery of concrete to a customers construction site, a driver was asked to discharge his load into a skip. This was to allow an excavator to 'manage' the material and allow the delivery point and area of use to be separate.

During discharge the excavator bucket moved the skip causing the drivers thumb to be crushed between the chute handle and the skip edge. The drivers thumb at the knuckle was severed and despite the driver being transferred to a specialist hospital, it could not be reattached.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



Poor Delivery Set Up

Click image to enlarge



Nip Point

LEARNING POINTS / ACTIONS TAKEN

- Mobile plant should never be operated in the close proximity of personnel.
- Operatives are reminded of our Zero Harm pledges; specifically 'Stop and ask if we feel at risk' - if in doubt suspend the task and contact the site manager.
- Always ensure a safe distance from the delivery chute and the material receptacle / intended destination.

LEARNING POINTS / ACTIONS IMAGES

[Request Futher Information](#)



[pdf document available](#)



[additional pdf document](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.