



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS

**HEALTH & SAFETY**  
spanning the  
Mineral Products Industry

Login

Register

 Information basket

▶ Home

▶ About  
this site

▶ BEST  
PRACTICE

▶ INCIDENT  
ALERTS

▶ HOT TOPICS  
& GUIDANCE

▶ TOOLBOX  
TALKS

▶ CPD  
reports

▶ Links

## INCIDENT ALERT

LOCATION:	MOBILE PLANT	ALERT STATUS:	<b>Critical</b>
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	25/03/2010
SUB ACTIVITY:	N/A	INCIDENT No:	00258

### TITLE

#### Death prompts telehandler warning

#### ACCIDENT / INCIDENT DETAILS

The British Health and Safety Executive has issued the following warning, which is endorsed by the MPA:

"QUARRY operatives are among those workers being warned not to operate variable-reach trucks, commonly known as telehandlers, if the right-hand side window is missing or broken, following a recent fatal incident in Scotland.

A 36-year-old man was apparently leaning through the broken window aperture of such a machine when he was crushed and fatally injured by the descending boom. It is the third such fatality in the last seven years."

#### ACCIDENT / INCIDENT IMAGES

#### LEARNING POINTS / ACTIONS TAKEN

The side window on telehandlers is designed to prevent operator access to the boom, but if the glass screen is broken or missing, operators may be tempted to lean out of the window aperture, for instance to adjust a mirror, and may inadvertently lower the boom on to themselves without being able to stop it.

The Health and Safety Executive has issued a Safety Notice recommending that machines in this condition be removed from use until the window has been replaced, and reminding users of their duty to carry out daily checks of the truck, which should include the condition of the cab windows.

#### LEARNING POINTS / ACTIONS IMAGES

#### [Request Further Information](#)

 [pdf document available](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.