



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



Login

Register

Information basket

▶ Home

▶ About
this site

▶ BEST
PRACTICE

▶ INCIDENT
ALERTS

▶ HOT TOPICS
& GUIDANCE

▶ TOOLBOX
TALKS

▶ CPD
reports

▶ Links

INCIDENT ALERT

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT / DELIVERY	DATE ISSUED:	22/02/2010
SUB ACTIVITY:	PRODUCT DELIVERY	INCIDENT No:	00254

TITLE

Dump Truck

ACCIDENT / INCIDENT DETAILS

Safety Alert received from Build Safe United Arab Emirates:

A dump truck operator was tasked to unload sand at site. He started by activating the hydraulics to raise the tipper and hurriedly climbed out from his cab to release the latches at the back of the truck.

He was unable to release both latches in time.

As the load shifted to the rear of the skip and the centre of gravity shifted the front wheels of the tipper came off the ground. This could have caused the tipper to over turn.

(see additional pdf document for further details)

ACCIDENT / INCIDENT IMAGES

LEARNING POINTS / ACTIONS TAKEN

Site vehicle risk assessments should be reviewed in light of the incident.

Review (and understand) truck operators manual.

Toolbox talks given to all drivers on safe tipping procedures.

Operators to ensure tailgate is unlocked before dumping and that vehicle is on reasonably level surface.

Banksman/spotter to be in attendance when any unloading is taking place.

Keep pedestrians and site vehicles apart.

LEARNING POINTS / ACTIONS IMAGES

[Request Futher Information](#)

[pdf document available](#)
[additional pdf document](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.