



REGISTER TODAY TO RECEIVE THE LATEST UPLOADS



- ▶ Home
- ▶ About this site
- ▶ BEST PRACTICE
- ▶ INCIDENT ALERTS
- ▶ HOT TOPICS & GUIDANCE
- ▶ TOOLBOX TALKS
- ▶ CPD reports
- ▶ Links

## INCIDENT ALERT

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT / DELIVERY	DATE ISSUED:	19/08/2011
SUB ACTIVITY:	MOBILE PLANT	INCIDENT No:	00304

### TITLE

### The Value Of Well Maintained Safety Devices

#### ACCIDENT / INCIDENT DETAILS

The true value of having well maintained edge protection, Roll Over Protection Systems (ROPS) and using Seatbelts was proven during a recent incident at a quarry.

While working on a muckshift operation a contractors dumper lost control while descending a steep section of haul road. The dumper ran up the haul road edge protection bunds a number of times and in each case the bund did exactly what it was designed to do in steering the dumper back on to the haul road.

Unfortunately the driver was unable to regain control and the dumper eventually jack knifed causing the front of the dumper to rotate through 270 degrees and the whole vehicle came to rest facing back up the hill down which it had just descended. Despite this the driver freed himself from the vehicle.


#### ACCIDENT / INCIDENT IMAGES

Click image to enlarge



**Yellow Paint Highlights Outer Wheel Path**

Click image to enlarge



**Dumper at Rest**

#### LEARNING POINTS / ACTIONS TAKEN

#### LEARNING POINTS / ACTIONS IMAGES

#### [Request Futher Information](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here for full terms.](#)