



**HEALTH & SAFETY**  
spanning the  
Mineral Products Industry

[REGISTER TODAY TO RECEIVE THE LATEST UPLOADS](#)

[Login](#)

[Register](#)

[Information basket](#)

[Home](#)

[About this site](#)

[BEST PRACTICE](#)

[INCIDENT ALERTS](#)

[HOT TOPICS & GUIDANCE](#)

[TOOLBOX TALKS](#)

[CPD reports](#)

[Links](#)

## INCIDENT ALERT

LOCATION:

TRANSPORT

ALERT STATUS:

Normal

ACTIVITY:

TRANSPORT / DELIVERY

DATE ISSUED:

16/01/2012

SUB ACTIVITY:

PRODUCT DELIVERY

INCIDENT No:

00323

### TITLE

#### Truck Mixer Fall

#### ACCIDENT / INCIDENT DETAILS

An accident occurred when a driver was alighting from his Truck-mixer vehicle in day light, on a dry day and on flat level ground.

Whilst coming down from his cab, the driver caught his foot on the bottom step, twisted and fell to the ground.

The Panel of Inquiry could only conclude that the accident happened because the driver did not maintain 3 points of contact until both feet were firmly on the ground before turning to complete his other tasks.

The bottom steps, have been damaged on some vehicles and removed. Furthermore, some steps have been taken off before they get damaged because of the cost of replacement.

#### ACCIDENT / INCIDENT IMAGES

[Click image to enlarge](#)



Bottom Steps

#### LEARNING POINTS / ACTIONS TAKEN

- Drivers must maintain 3 points of contact
- Ensure vehicle steps provided by the manufacturer are on the vehicle
- Ensure all vehicle steps are clean, free from debris and collision defects

#### LEARNING POINTS / ACTIONS IMAGES

[Request Futher Information](#)

[convert this page to a pdf](#)

[Go back to search criteria](#)

The Mineral Products Association hereby grant visitors to this website access to these pages conditional upon your agreement to indemnify us and not hold us liable for the result of any actions you may take based on the information contained herein. While every effort is made to ensure the accuracy of the content of this website, this cannot be guaranteed. [Click here](#) for full terms.