

WEEKLY INCIDENT SUMMARY

Week ending Friday 5 June 2020

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of incidents and our comments to Industry.

TYPE	NUMBER
Reportable incident total	56
Summarised incident total	2

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0037487 Underground metals mine	<p>A crew was conducting a flush of a paste pipe reticulation system between levels.</p> <p>Upon inspection of the system at one level, there were no visible signs of the flush. Following confirmation from the paste plant that the pressure in the pipes had dropped from a peak of 350kPa to 60kPa, the crew confirmed with the paste plant that they wanted the pressure released from the system.</p> <p>The crew proceeded to another level to remove a blast cap for inspection, and while a crew member was undoing clamps on the pipe, the blast cap blew off. This released the built-up water pressure in the system. One worker</p>	<p>Relief valves should be installed at inspection points in reticulation systems to dissipate pressure before removing any caps from the system.</p> <p>Mine operators should review how workers and supervisors are trained to recognise the potential hazards associated with all energy sources. This is especially important when there is the potential for unexpected stored energy, associated with blockages, to be released without warning.</p>

reported temporary hearing loss from the incident. No other injuries were reported.



Dangerous
incident
IncNot0037506
Underground
coal



Fire or explosion

A mine worker saw a flash from a 1000 volt conveyor drive motor junction box. The electrical protection system activated and shut down the conveyor. There were no injuries.



This incident is being investigated and further information may be published at a later date.

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2020 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (June 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference	DOC20/441150
Mine safety reference	ISR20-23
Date published	12 June 2020
Approved by	Chief Inspector Office of the Chief Inspector