

### SECTION A - INCIDENT ALERT

#### Incident Details


Incident no: INC-0161335	Date: 01/03/2021	Time: 1509hrs
Department: Zinc	Asset name : George Fisher Mine	Country: Australia
Incident Title: Operator working at height on top of a loader with no fall restraint and engine running.		
Related Hazard: 2. Working at Height	For "Other" describe:	
Process Safety Management related Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Mobile Equipment and Energy Isolation	
The incident involved: <input checked="" type="checkbox"/> Employee <input type="checkbox"/> Contractor:	Legal Consulted (Actual Cat 4 & 5 incidents): <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

#### Brief Incident Description

An Operator was observed on video footage exiting the cabin and climbing on top of an underground loader via the articulation area/midship steps and rear steps to adjust vent.

Whilst Operator was on top of the loader, the engine was still running. The Operator was not safeguarded by a fall prevention system or protection device.

On review of the footage, the Operator was observed to conduct the activity on more than one occasion.



#### Consequences

No injuries occurred with this incident.

Possibility of a fall from of over 2m height onto the ground.

Possibility of crushing injuries whilst entering articulation area with engine still running.

#### Immediate Actions

Operator stood-down pending investigation.

The incident investigation commenced.

#### Approved by

**Name:** Rebecca Roper  
**Phone:** +61 7 4744 6218

**Title:** Manager - George Fisher Operations  
**Email:** rebecca.roper@glencore.com.au

This HSEC Alert is not intended to be comprehensive or provide definitive safety or environmental advice. The information may change upon further investigation and more information becoming available.

The information contained in the alert should be factual and not contain opinions or speculation.