




Fatality Alert

MINE FATALITY – On April 22, 2021, a miner was fatally injured when leaving the mine site in his personal pickup truck. The manual swing barrier gate was partially closed. A gate pole entered the truck's windshield as the pickup truck approached, striking the victim and causing fatal injuries.



Best Practices

- Ensure that manual swing barrier gates can be secured when opened or closed to prevent unintentional movement.
- Paint or tape swing barrier gates with reflective and distinguished markings to differentiate them from their surroundings. Install additional lighting near barrier gates.
- Conduct thorough travelway examinations to identify and mitigate hazards.
- Establish safe traffic patterns with proper signage.
- Be alert to road conditions and always keep a clear line of sight.
- Maintain proper speed for road conditions.

This is the ninth fatality reported in 2021, and the fifth classified as "Powered Haulage."

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553