

## WORKPLACE FATALITY

# Truck driver dies at open cut mine

**Incident date:** 17 January 2018

**Event:** Non-work-related death at an open cut coal mine

**Location:** Glendell Mine, Hunter Valley, NSW

## Overview

A worker was driving an articulated dump truck as part of rehabilitation activities at the mine. After being loaded with topsoil, the dump truck was seen to veer off the haul road and come to a stop about 250 metres away. The driver was found unresponsive and died despite the efforts of his co-workers and ambulance officers to resuscitate him.

## The mine

The Glendell Open Cut Mine is at Ravensworth, in the Upper Hunter Valley, about 25 kilometres northwest of Singleton, NSW.

The mine is owned and managed by Mt Owen Pty Limited, on behalf of Glencore Coal Australia Pty Limited.

## The incident

The worker, aged 39, was employed by a contractor.

The worker was operating an articulated dump truck to move topsoil as part of regeneration works at the mine.

After being loaded with topsoil, nearby co-workers observed the dump truck veer off the haul road and cross a contour drain. The dump truck continued a further 250 metres across rehabilitated land before coming to a stop.

The co-workers rushed to the scene and found the worker unresponsive in the dump truck cabin.

Attempts to resuscitate the worker were unsuccessful.

## Investigation outcome

The NSW Resources Regulator has conducted an investigation into the circumstances of the worker's death. As a result of the information obtained during the investigation, the Resources Regulator does not consider the worker's death to be work-related.

## Safety observations

Mine and petroleum site operators are reminded of their duty to identify hazards and manage risks to health and safety in accordance with the provisions of the *Work Health and Safety Act 2011* and *Work Health and Safety (Mines and Petroleum Sites) Act 2013* and Regulations.

Mine operators should have effective health monitoring programs in place to ensure workers are healthy and fit to work at mining operations and in mine environments. Regular medical examinations should be undertaken by qualified medical practitioners.

Persons conducting a business or undertaking (PCBUs) should provide information to workers about healthy lifestyles and fitness-for-work programs.

Workers should maintain a healthy lifestyle and be fit to undertake the work they perform.

## Further information

Please refer to the following guidance materials:

- Health management: [Health management overview](#)
- Health control plan fact sheet: [Effective controls to ensure fitness for work](#)

## About this information release

The Resources Regulator has issued this information to draw attention to the occurrence of a death in the mining industry. The investigation is now closed.

Go to [www.resourcesregulator.nsw.gov.au](http://www.resourcesregulator.nsw.gov.au) to:

- learn more about our work on major investigations and emergency response
- view our publications on other major investigations
- find your local mine safety office, where you can contact our team of mine safety inspectors.

# Investigation Information release

NSW  
RESOURCES  
REGULATOR

## Office use only

CM9 reference	DOC18/806819
Mine safety reference	IIR18-13
Published	7 December 2018
Authorised by	Brian Glendenning, Director Major Investigations

© State of New South Wales through the NSW Department of Planning and Environment 2018.

This publication is copyright. You may download, display, print and reproduce this material in an unaltered form only (retaining this notice) for your personal use or for non-commercial use within your organisation. To copy, adapt, publish, distribute or commercialise any of this publication you will need to seek permission from the NSW Department of Planning and Environment.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (December 2018). However, because of advances in knowledge, users are reminded of the need to ensure that information upon which they rely is up to date and to check currency of the information with the appropriate officer of the NSW Department of Planning and Environment or the user's independent advisor.