

Fatality Alert



MINE FATALITY – On June 1, 2020, a contract truck driver died after falling from the top of his trailer. The victim received first aid/CPR at the scene and passed away after being transported to a local hospital.



Best Practices

- **Discuss work procedures**; identify all potential hazards to do the job safely.
- Train everyone to recognize fall hazards and ensure that safe work procedures are discussed and established.
- Include safe truck tarping requirements in site-specific hazard training.
- Provide truck tarping safe access facilities where needed.
- Provide an effective fall arrest secure anchorage system. Ensure that people wear and attach fall protection connecting devices where there is a danger of falling.
- Use automatic tarp deploying systems to prevent people from working from heights.

This is the 8th fatality reported in 2020, and the third classified as "Slip or Fall of Person."

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.